

CATEGORY: PARTS (CORES)

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: STEERING RACK CORE REQUIREMENTS

Since the introduction of the reproduction steering rack, we have been advised by our supplier that it may not be cost-effective in the future to have pinion gears reproduced. Therefore we have added a "core charge" to the steering rack and requiring return of the pinion gear ONLY for a refund of the core charge.

Removal of the pinion gear is accomplished by removing the two bolts holding the oval shaped plate in position on the top of the rack as shown below. Once this plate is removed, the pinion gear should pull out, perhaps requiring a slight turning motion when pulling.

Clean excess grease/oil off the pinion gear and place it in a padded envelope. Insure for the core value and ship to DMC (Texas) along with a copy of your invoice for rapid processing and refund of paid core charges.

